



Tapping & Drilling Machines

TM1100, DM Series, Feed Tap, and DM3MECH



NOTES:

- TM1100, CDTM and DM Series Machines require cutters and drills that are sold separately.
- "+" Symbol in chart indicates recommended cutters/drills to be purchased.
- Feed Tap™ (FT series) machines on this chart include 4 cutters in FT2000 series, but 2 cutters in FT1000 series.
- Power drives available for TM1100 and DM Series (DM1100/DM2100) tap/drill machines.

¹ For 2" Iron Body Gate Valves, Extended Boring Bar #99390 is REQUIRED for DM machines with 2" NPT adapters.

² For 2" Iron Body Gate Valve and Feed Tap™ machine, user must supply 2" male x 1" female bushing.

³ DM3MECHB is a base model with NO hole saws or arbor. Most hole saw brands fit this machine.

VIDEO TRAINING

Drilling Machines | Feed Tap™ Drilling Machine | Direct Tapping Machine